



JUSCO
quality services for life
A TATA Enterprise

DEVELOPMENT OF RETAINING WALL AT TATA STEEL LIMITED JUSCO JAMSHEDPUR


BEFORE


AFTER

Cross Section Drawing for Retaining Wall



TYPICAL CROSS SECTION









Dismantling of Existing Brick Wall










Demarking the Area of Excavation









Excavation of Base







Compaction of base





Laying of Geo Cells

















Back Filling activities






NO MASK
NO ENTRY



FINAL SITE CONDITION AFTER 10 MONTH




Emergency Vehicle Good Observation at Site



Good Observation at Site

TATA STEEL UTILITIES AND INFRASTRUCTURE SERVICES

Dept: Town Services Date: 17/03/2021 Location: Dimna Geo Cell boundary wall works
Vendor: M/s Saghan Commercial Site Engg: Jitendra Yadav



Good Point Observed:

1. Ambulance with stretcher was available at site to attend during emergency.
2. Net was provided to protect from loose boulders.
3. Document related to safety like PTW, SWP, Training Record, GIS clearance etc was available at site.
4. Various safety poster were displayed.
5. Work was in progress under close supervision.
6. All the workmen were having valid gate pass.
7. EPRP was available at site.

THANK YOU



SHAGAN COMMERCIALS

Contact us at:

Head Office
40 Mishra Para, Jharia, Dhanbad, Jharkhand – 828 111

Corporate Office
1st Floor, 4B, Wood Street, Kolkata West Bengal – 700 016

Ph No: 8092200004 / 05/ 06
Email id – headoffice@scvs.in